


SI5500 - User Manual





GENERAL

TRADEMARKS AND COPYRIGHTS

Information in this document is subject to change without notice.

No part of this document may be reproduced or transmitted in any form or by means, electronic or mechanical, for any purpose, without the express permission of Solartron Metrology.

© 2012 Solartron Metrology Ltd. All rights reserved. Microsoft®, Windows®XP, Windows®Vista, Windows®7, Excel®, VBA and VB are registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.

Orbit® is a registered trademark of Solartron Metrology Ltd

CONTACT INFORMATION

For updated information, troubleshooting guide and to see our full range of products, visit our website:

<http://www.solartronmetrology.com>

TABLE OF CONTENTS

1	INTRODUCTION	7
2	SCOPE	7
3	NAVIGATE THIS DOCUMENT	7
4	SAFETY SUMMARY	8
5	GLOSSARY OF TERMS AND BASIC SYSTEM INFORMATION	9
5.1	TERMS ASSOCIATED WITH SI5500 Read out	9
6	ELECTRICAL INSTALLATION	11
7	DISPLAY AND KEYPAD	12
7.1	OPERATE SCREEN.....	12
7.2	Switching to the single channel configuration for the selected channel.....	18
7.3	Keypad functionality in single channel or multi channel configuration	18
7.4	GAUGING Mode Screen.....	19
7.5	AUTOSENSE mode SCREEN	20
8	MENU SCREEN	21
8.1	SetUp Menu	22

8.2	Display Configuration Menu	23
8.3	Probes Menu	24
8.4	computed measurement.....	25
8.5	Measurement mode	28
8.6	Preset/Limits Menu	29
8.7	Input/Output Menu	30
8.7.1	Pin Details of Discrete Outputs	31
8.7.2	Pin Details of Discrete Inputs	31
8.8	PRINT Options.....	33
8.8.1	PRINT FORMAT	35
8.9	Serial Port Menu.....	38
8.10	Advanced Measurement Mode Menu	39
8.10.1	PEAK MODE	41
8.11	Utilities menu	42
8.11.1	LOGGING SETTINGS	43
8.11.2	SCREEN SETTINGS	45
8.11.3	ABOUT	45
9	SETTING UP PROBES	46
9.1	setup steps before Starting measurement	47
10	SERIAL COMMANDS	49

11	MEASUREMENT AND TIMING INFORMATION	52
12	RETURN OF GOODS.....	53

1 INTRODUCTION


This manual specifically caters for the SI5500 read out with Orbit Interface.

2 SCOPE

The SI5500 read out can interface **up to 31 Orbit Sensors** and communicates through Orbit Serial Protocol (via Orbit Interface). It can interface with Orbit Digital Probes, Linear Encoders and Encoder Input Modules. The readings from the sensors are displayed on the front panel LCD display. SI5500 includes a unique feature of configuring user defined formulas/expressions for each of the measurement channel. A **maximum of 31 measurement channels** are supported. The read out can be configured through a 9-button keypad (3x3). Basic Input Output is provided by discrete lines. A RS232 serial interface is provided for printing the current readings.

3 NAVIGATE THIS DOCUMENT

This is a large document, to aid electronic navigating the document; the following Navigation tip may be useful:
It is often necessary to jump to another item and then go back to where you jumped from.
This can be done in Adobe Reader by using the 'Previous Page View' button:



'Previous Page View'
Button

Other PDF readers will have a similar 'Previous Page View' option.

4 SAFETY SUMMARY

WARNING statements identify conditions or practices that could result in personal injury or loss of life.

CAUTION statements identify conditions or practices that could result in damage to the equipment or other property

Symbols in this manual



Indicates cautionary or other information

Warnings and Cautions

Warning: Do not operate in an explosive atmosphere.

Warning: this equipment is not intended for safety critical applications

Warning: Do not operate without covers

Warning: do not exceed maximum ratings as specified in this document under individual modules.

Caution: Low Voltage

This equipment operates below the SELV and is therefore outside the scope of the Low Voltage Directive

Service and Repair



CAUTION: This equipment contains no user serviceable parts. Return to supplier for all service and repair

All of the Products are CE marked and comply with Low Voltage Directive (1997) standards.

5 GLOSSARY OF TERMS AND BASIC SYSTEM INFORMATION

5.1 TERMS ASSOCIATED WITH SI5500 READ OUT

Display

The Liquid Crystal Display mounted on the front panel of the read out providing displayed information

Keypad

The 9-button keypad (3x3) mounted on the front panel of the read out allowing functional and menu navigation

Discrete Inputs

Digital lines into the read out which allows remote control of certain parameters/functionalities

Discrete Outputs

Digital lines output from read out that can be used to drive external loads. These can be with either NPN or PNP configuration

Serial Interface

This is a RS232 bus that is used to print the reading in ASCII format (as defined in this manual).

Digital Probe

This is a standard Solartron product that can be connected to the read out through Orbit Interface.

EIM

Encoder Input Module – A standard Solartron product that is used to interface with rotary encoders and can be read through Orbit Interface.

Linear Encoder (LE)

Highly accurate optical gauge that can be read out through Orbit Interface.

Measurement Mode

This information represents the current measurement mode of the channel. It can take the values of ABS(Absolute), TARE(ZERO), PRE(Preset)

ABS(Absolute) – In this mode the displayed reading is same as the current absolute reading.

TARE(ZERO) – In this mode the displayed reading is referenced to a “Zero” value.

PRE(Preset) – In this mode the displayed reading is referenced to a user defined value.

Operation Mode

This information represents the mode in which the measurement channel is operating. It can take the values of TRACK, PEAK+, PEAK-.

TRACK – Tracks the current reading of the measurement channel

PEAK+ – Tracks the maximum value of the measurement channel

PEAK- – Tracks the minimum value of the measurement channel

Sensor/Orbit Sensor

This refers to Orbit Digital Sensor from Solartron. It can be one of Digital Probe or Linear Encoder or EIM sensor module.

6 ELECTRICAL INSTALLATION

This section describes how to connect the unit.

I/O Connector


Refer to Discrete Lines section for pin details and input/output schematic details

RS232 COMM Connector

Refer to RS232 section for pin details

24V DC Input

Connect the DC power adapter supplied as an accessory along with the read out.



Orbit Communication Interface Ports

Connect one end of the RS485 cable to one of the ports and the other end to the Orbit network.



Orbit Network Stack

Orbit Digital Probes of up to **31 sensors** can be connected together. SI5500 read out supports interface of DP probes (Spring Push/Pneumatic), Linear Encoders and Encoder Input Modules.



7 DISPLAY AND KEYPAD

SI5500 operates in four modes of display namely: OPERATE SCREEN, MENU SCREEN, GAUGING SCREEN and AUTONSENSE SCREEN


7.1 OPERATE SCREEN

The calculated readings are displayed in this mode. The operate screen can be of Single Channel Bar Display, Dual Channel Bar Display, 4-Channel Bar Display, 8-Channel Bar Display, 16-Channel Bar Display, 8-Channel Text Display, 16-Channel Text Display. User can select the required type of display through "Display Configuration Menu".

In the multi-channel configuration, user can scroll through the required set of channels using ◀ and ▶ arrow keys. The scrolling is not possible in single channel configuration.


- Dual Channel Display Configuration

This mode displays two consecutive channel readings in bar panel mode. The blue cursor on top of the bar indicates the current selected channel. The limits and the formula configured for the measurement channel will be missing on the display. User has to switch to Single Channel Display Configuration for getting complete information about the measurement channel.



- 4-Channel Display Configuration

This mode displays 4 consecutive channel readings in bar panel mode. The blue cursor on top of the bar indicates the current selected channel. NOTE that the resolution of max/min range values is limited to 3 decimal point resolution due to constraint in the available display area. User can switch over to Single Channel Display Configuration for getting complete information about the measurement channel.



- 8-Channel Display Configuration

This mode displays 8 consecutive channel readings in bar panel mode. The blue cursor on top of the bar indicates the current selected channel. The resolution of max/min range values is limited to 3 decimal points only due to constraint in the available display area. User can switch over to Single Channel Display Configuration for getting complete information about the measurement channel. The measurement mode and channel operation modes are abbreviated as a single text in this mode. Below are the abbreviated values:


- TR_AB – Operation mode is TRACK, Measurement mode is ABS
- TR_ZE – Operation mode is TRACK, Measurement mode is ZERO
- TR_PR – Operation mode is TRACK, Measurement mode is PRESET
- P+_AB – Operation mode is PEAK+, Measurement mode is ABS
- P+_ZE – Operation mode is PEAK+, Measurement mode is ZERO
- P+_PR – Operation mode is PEAK+, Measurement mode is PRESET

- P_AB – Operation mode is PEAK-, Measurement mode is ABS
- P_ZE – Operation mode is PEAK-, Measurement mode is ZERO
- P_PR – Operation mode is PEAK-, Measurement mode is PRESET



- 16-Channel Bar Display Configuration

This mode displays the 16 consecutive channel readings in bar mode. The blue cursor on top of the bar indicates the current selected channel. NOTE that in this mode the readings and no other information related to the measurement channel is displayed. The reading is indicated only through the bar fill according to the current reading. This mode can be mainly used to find out which channels are out of limits/range. User can switch to Single Channel Configuration for getting the complete information about that channel.



- 8-Channel Text mode configuration

This mode displays the 8 consecutive channel readings in text mode. The blue cursor on left of the channel reading indicates the selected channel. User can switch to Single Channel Configuration for getting the complete information about that channel.

● + 1.7669	mm	C1	TRACK ABS
+ 2.7515	mm	C2	TRACK ABS
+ 3.2959	mm	C3	TRACK ABS
+ 4.2344	mm	C4	TRACK ABS
+ 0.8052	mm	C5	TRACK ABS
+ 7.9102	mm	C6	TRACK ABS
+ 6.2287	mm	C7	TRACK ABS
+ 1.8995	mm	C8	TRACK ABS


- 16-Channel Text Mode Configuration

This mode displays the 16 consecutive channel readings in text mode. The blue cursor on left of the channel reading indicates the selected channel. User can switch to Single Channel Configuration for getting the complete information about that channel.

● + 1.7669	mm	C1	+ 0.0000	mm	C9
+ 2.7514	mm	C2	+ 0.0000	mm	C10
+ 3.2959	mm	C3	+ 0.0000	mm	C11
+ 4.2344	mm	C4	+ 0.0000	mm	C12
+ 0.8052	mm	C5	+ 0.0000	mm	C13
+ 7.9102	mm	C6	+ 0.0000	mm	C14
+ 6.2287	mm	C7	+ 0.0000	mm	C15
+ 1.8995	mm	C8	+ 0.0000	mm	C16

- Single channel configuration

This mode displays all the properties of the measurement channel. User can switch to this mode to get all the required information of the selected channel.



NOTE:

1. If any one of the sensor/multiple sensors used in the formula is in OverRange/UnderRange condition, then an "ERROR" status is displayed in RED color instead of the current reading. The bar will be drawn with full scale in RED color.
2. If any of the sensors is not connected or not notified, then an "ERROR" status will be displayed for all the channels using that particular sensor in their formula. The bar will be drawn with full scale in RED color.
3. **OSError:** This error occurs when one or more Linear Sensors used in the formula for the corresponding channel reports "OverSpeed Error". When this error occurs the bar is drawn with full scale in RED color. To reset this error, select the channel (in case of multi-channel configuration scroll the cursor to that channel) and then press ZERO key. It will reset the error and note that the reading from Linear Sensor is automatically re-zeroed. However it will not re-adjust (or re-Zero) the displayed reading if the channel is in ZERO mode. This operation has to be explicitly performed by the user through ZERO key.

7.2 SWITCHING TO THE SINGLE CHANNEL CONFIGURATION FOR THE SELECTED CHANNEL

To switch to single channel mode from any multi-channel configuration below steps has to be followed:

- Use ◀ and ▶ arrow keys in the multi-channel configuration to select the required channel.
- Press ENTER key to display the selected channel in single channel configuration mode.
- To go back to the previous multi-channel display configuration, press ENTER key again.


7.3 KEYPAD FUNCTIONALITY IN SINGLE CHANNEL OR MULTI CHANNEL CONFIGURATION

When the current display is of Single Channel or Multi-channel configuration mode, the metrology functions are performed through keypad buttons. The functionality of each key is described in the table below:

KEY	DESCRIPTION
MENU	Switches to Set Up MENU Screen.
▲ Arrow Key	Enables PRESET on the selected channel/on all channel depending on “ZERO/PRESET all” setting in “Display Configuration” menu.
▼ Arrow Key	Performs PEAK RESET on the current channel. Continuous press of more than 1 second will perform PEAK RESET on all the channels.
PRINT Key	Prints the reading according to the mode selected. Refer to the PRINT Options section for information on PRINT options configuration
◀ Arrow Key	Scrolls to the previous channel when the display is in multi-channel configuration. Hold the key for more than 300ms for a continuous scroll to the previous channels. No operation in single channel configuration.
ENTER Key	Switches to single channel configuration for the selected channel from multi-channel configuration. An ENTER key press again will switch back to the multi-channel configuration. NOTE THAT when single channel configuration is selected through “Display Configuration” MENU Screen, there is no functionality for ENTER key.
▶ Arrow Key	Scrolls to the next channel when display is in multi-channel configuration. Hold the key for more than 300ms for a continuous scroll to the next subsequent channels. No operation in single channel configuration.
ZERO Key	Perform the ZERO operation on the current selected channel or on all channels depending on “ZERO/PRESET all” setting in “Display Configuration” menu.
PEAK/TRACK Key	Changes the operation mode between PEAK+, PEAK- and TRACK on the selected channel.

7.4 GAUGING MODE SCREEN

This screen displays the result when Gauging mode is enabled. Gauging mode is used to check if all the selected number of channels is within limits. The count of channels to be used for gauging mode can be configured through “Advanced Measurement Mode” menu screen.



If all the channels selected for scanning are within limits, then “PASS” status is displayed. If one or more number of channels is outside limits, then “FAIL” status is displayed.

User can select “Scan” option to display the channel in Single Channel Configuration mode. ▲ and ▼ arrow keys can be used to scroll through the different channels. This mode is called as STATIC mode. NOTE THAT PRESET, PEAK/TRACK and PEAK RESET functionalities does not work in STATIC mode. ZERO and PEAK/TRACK key functions similar to that of Single Channel Configuration. To exit STATIC mode, use PEAK/TRACK key.


“Search” option is used to display the channel/channels which are outside limits. If multiple channels are outside limits, then the first channel is displayed in single channel configuration mode for the configured amount of time. After that the display scrolls to the next channel which is out of limits. At the end, the display changes back to the result screen. The delay time for which each of the channels has to be displayed can be configured through “Advanced Measurement Mode” menu screen.

If all the channels are within limits then screen with “No Faults Found” message is displayed for the configured amount of delay time and switches back to the result screen.

“LOAD” option is used to enable the PRESET values for the measurement channels. If “LOAD” option is selected once again, it removes PRESET values.

7.5AUTONSENSE MODE SCREEN

This screen displays the result when Autosense mode is enabled. Autosense mode is used to automatically select the channel which is within limits. The count of channels to be used for scanning can be set through Autosense Mode menu screen. When a channel is within limits, it is displayed in Single Channel Configuration mode. If none of the channel is within limits, then the status message "Probes Parked" message is displayed.



NOTE: When more than one channel is within limits, the first channel is displayed in single channel configuration mode. There is no scrolling possible to switch to the next channel.

The keypad functions the same as for Single Channel Configuration mode.

8 MENU SCREEN

The MENU screens are used to set up/configure the read out. Menu Screen can be activate through MENU key button on the keypad. The current screen is stored and displayed back when MENU Screen mode is exit.

In MENU Screen mode the keypad functionality is as per the table below:

KEY	DESCRIPTION
MENU	Exits MENU Screen mode.
▲ Arrow Key	Scrolls UP. Hold the key for more than 300ms to scroll UP continuously.
▼ Arrow Key	Scrolls DOWN. Hold the key for more than 300ms to scroll DOWN continuously.
PRINT Key	No Operation.
◀ Arrow Key	Scrolls to the right side. Hold the key for more than 300ms to scroll continuously.
ENTER Key	To select the option and also for number editing. Refer to the example below.
▶ Arrow Key	Scrolls to the left side. Hold the key for more than 300ms to scroll continuously.
ZERO Key	Used only in Formula Edit Menu Screen. Will erase the complete formula so that the user can enter the required formula from the beginning.
PEAK/TRACK Key	Used only in Formula Edit Menu Screen. Acts as a backspace key. Erases a single token (operator/operand) in the formula. For e.g. Consider the formula "A+sinB" and the current cursor location is at B. Press of this key will erase "sin" token and retains the remaining tokens in the formula string. The resultant formula string will be "A+B".

Example of editing a number:


There are many menu screens where number/range values are present. Below is the procedure for editing the same.
Consider the number +010.00000.

Key	+	0	1	0	.	0	0	0	0	0	Cursor is at first position. Default position at the start.
ENTER	+	0	1	0	.	0	0	0	0	0	ENTER key will start edit mode.
▲	-	0	1	0	.	0	0	0	0	0	UP arrow key will change the sign of the number.
▶	-	0	1	0	.	0	0	0	0	0	RIGHT arrow key will change the current position to the next digit '0'
▶	-	0	1	0	.	0	0	0	0	0	RIGHT arrow key will change the current position to the next digit '1'
▲	-	0	2	0	.	0	0	0	0	0	UP arrow key will increment the number.

ENTER	-	0	2	0	.	0	0	0	0	0	ENTER key will stop edit mode. The final number (-020.00000) will be saved and used further.
-------	---	---	---	---	---	---	---	---	---	---	--

8.1 SETUP MENU

The main SetUp Menu has two pages (Page1 and Page2).



8.2 DISPLAY CONFIGURATION MENU

Display Configuration Menu	OPTIONS
Display Config	1Ch, 2Ch, 4Ch, 8Ch Bar, 8Ch Txt, 16 Ch Bar, 16Ch Txt
Places after DP	1, 2, 3, 4, 5
Bar Offset	+000.00000
Bar AutoRange	OFF, ON
ZERO/PRESET all	OFF, ON
Last Digit Step	1, 2, 3, 4, 5
Exit Menu	

NOTE: The “Display Config” menu item is a list box and the options under this item can be selected through ◀ and ▶ arrow keys. The options for this menu item are listed with a comma in between the options. The same convention will be followed further in this document. All the options which are separated by a comma is a list box and can be selected through ◀ and ▶ arrow keys.

“ZERO/PRESET all” menu option enables the setting of performing ZERO/PRESET operation on single channel or on all channels.

Last Digit Step – Defines the minimum step resolution for the reading displayed. The displayed reading is changed only in multiples of the configured “Last Digit Step” configuration setting. For e.g. If the setting is set to ‘2’ and the reading changes from 7.5264 to 7.5267 the reading on the display is changed to **7.5266** and not **7.5267** since it is not multiple of 2.

NOTE: To disable the “Last Digit Step” functionality, set it to ‘1’.

8.3 PROBES MENU

Probes Menu – Sensor **A** ← Sensor number: Varies from 'A' to 'Z' and from 'a' to 'e'.

OPTIONS	
Probe Type	Orbit
Direction	Retract+, Extend-
Range	+123.00000
Probe ID	ABCDEFGHIJ
Resolution	14-bit, 16-bit, 18-bit
Pulses/Rev	12345

These fields are not user editable- Will be filled automatically according to the sensor Notified.
NOTE: The Pulses/Rev option is valid only for EIM sensor type and will not appear for other Orbit Sensor types. The Resolution and Pulses/Rev options do not appear on start-up and will be visible if a valid probe is notified.

Notify Back Next Menu

Probes Menu is used for setting up the probes. To Notify a probe follow the below procedure:


- Select the direction type. For Spring-Push probes: it has to be set to “Retract+”, for pneumatic probes: it has to be set to “Extend-”.
- Select “Notify” option. An on-screen tip will also be displayed on the screen.
- Move the probe tip to get notified.
- After notify command is successful, the “Range”, “Probe ID”, “Resolution”, “Pulses/Rev” parameters gets populated according to the sensor type.

NOTE:

- To Notify the probe tip has to be moved such that the readings change by about 1%. After moving the probe tip, it takes about 500ms to update the data on the display.

- Resolution can be changed only for **DP type probes**. It is also **not possible** to change if a sensor is in **Difference Mode**. Difference mode is started if MAX or MIN or DIFF math formula is applied on the particular probe.

8.4 COMPUTED MEASUREMENT



This screen is used to edit/enter the formula for the corresponding channel.

Opr, Opd, Num, Math options provides a pop-up window containing various mathematical operators, trigonometric functions and sensor numbers (used as operands for mathematical or trigonometric functions) defined in the table below.

Opr - +, -, *, /, (,), , Exit

Opd - A, B, C, D, E, F, G, H, I, J, K, L, M, N, O, P, Q, R, S, T, U, V, W, X, Y, Z, a, b, c, d, e, Exit

Num - 0, 1, 2, 3, 4, 5, 6, 7, 8, 9, Exit

Math - sin, cos, tan, inlog10, inloge, log10, loge, Mx, Mn, MAX, MIN, DIFF, Exit

User has to use ◀, ▶, ▼ and ▲ arrow keys to scroll through the options displayed in Opr, Opd, Num, Math pop-up windows. The required option can be selected through ENTER key. The selected option is inserted at the current indexed location in the formula string.

TIP:

1. It is not necessary to exit the pop-up window displayed before opening the new pop-up window. User can scroll to the next required option using ▼ ▲ ▶ and ◀ arrow keys. Whenever the next option is selected before exiting the current pop-up window it is taken care to erase the current pop-up and the new pop-up window will be displayed.

For eg: If user is in “Opd” pop-up window display and wants to open “Math” pop-up window, it is not necessary to scroll through all the way to “Exit” option, close the window and then select the Math option. Instead user can use ▲ and ▶ arrow key to scroll to “Math” option and select the same to display “Math” operations pop-up window.

2. Flexibility has been provided even to scroll through the formula expression string, without closing the pop-up window displayed. User can use ▲ arrow key to scroll to the formula string and then ◀ and ▶ arrow keys to index to the required position in the formula string.
3. If a measurement channel is not used, leave the formula field blank by erasing the complete formula. This will yield a faster performance.

8.5 MEASUREMENT MODE

Measurement Mode Menu	OPTIONS
Channel Nr	C1, C2, C3,, C31
Measure Mode	TRACK, PEAK+, PEAK-
Reset Mode	Manual, Automatic
Trigger Time(ms)	12345
Trigger Level	+000.000000
Exit Menu	

These options are applicable only for PEAK+ and PEAK- measure mode options. It will be displayed only if the corresponding channel is in PEAK+ or PEAK- measurement mode.

NOTE: Trigger Time has to be a multiple of 20ms


This menu is used to configure the measurement mode of the channel.

If “Reset Mode” is set to Manual option, then the peak value is reset through ▼ arrow key.


If “Reset Mode” is set to Automatic option:

- In PEAK+ mode, peak value is reset to the current reading if it goes **below** the configured trigger level for the configured trigger time period
- In PEAK- mode, peak value is reset to the current reading if it goes **above** the configured trigger level for the configured trigger time period

8.6 PRESET/LIMITS MENU



8.7 INPUT/OUTPUT MENU



SI5500 supports 6 discrete inputs and 6 discrete outputs. The discrete outputs can be mapped to any channel number through menu screen shown above.

“OK” Control Function: Output is set when the reading for the associated channel is within limits.

“Over” Control Function: Output is set when the reading for the associated channel is above upper limit or above max. range (OverRange condition).

“Under” Control Function: Output is set when the reading for the associated channel is below lower limit or below min. range (UnderRange condition).

TIP: If any output is not used, set it to “None”.

8.7.1 Pin Details of Discrete Outputs

PIN No.	Description
1	Out1
14	Out2
2	Out3
15	Out4
3	Out5
16	Out6
4	Isolated O/P Common


8.7.2 Pin Details of Discrete Inputs

The functionality of discrete inputs depends on the “Inputs Config” type configured. Below is the table explaining the discrete inputs functionality:


PIN No.	Config1	Config2
17	ZERO Edge Input type. When this input is set active, it will ZERO the current selected channel or all channels according to the ZERO/PRESET all configuration	ZERO Edge Input type. When this input is set active, it will ZERO the current selected channel or all channels according to the ZERO/PRESET all configuration
5	PRESET Edge Input type. When this input is set active, PRESET operation will be performed on the current selected channel or all channels according to the ZERO/PRESET all configuration	PRESET Edge Input type. When this input is set active, PRESET operation will be performed on the current selected channel or all channels according to the ZERO/PRESET all configuration
18	PRINT For Edge Input type – It sends single PRINT data onto	PRINT For Edge Input type – It sends single PRINT data onto

	RS232 port. For ACTIVE Input – It sends continual PRINT stream of data onto RS232 port.	RS232 port. For ACTIVE Input – It sends continual PRINT stream of data onto RS232 port.
6	LOG Starts data logging	Not Used
19	PEAK RESET Edge Input type. Performs complete PEAK RESET on all the channels	Not Used
7	PEAK TOGGLE Edge Input type. Changes the mode of the current selected channel between PEAK+/PEAK-/TRACK. Similar to giving input through PEAK/TRACK key from the keypad	Not Used
20	Isolated I/P Common	Isolated I/P Common

Discrete Inputs and Outputs Schematic:




Discrete Outputs Schematic



Discrete Inputs Schematic

8.8 PRINT OPTIONS



Single PRINT will send the data onto RS232 only once.

Continuous PRINT will send data onto RS232 continuously.

The PRINT key or the discrete input functionality depends on the current mode in which SI5500 is operating. Below table summarizes the same:

Print Mode	OPERATE SCREEN	GAUGING MODE	AUTOSENSE MODE	PEAK MODE
This Reading	Prints Current Readings of all displayed channels	If in SCAN mode i.e. current display is Gauging Mode result Screen, no	Prints Current Reading of the displayed channel within limits.	When the unit is in “ <i>acquisition phase</i> ”, the currently stored readings

		<p>print occurs.</p> <p>If in STATIC mode i.e. “Scan” option is selected through Gauging Mode result Screen, current displayed channel reading is printed.</p>	<p>If there is no channel within limits, no information will be printed.</p>	<p>are printed.</p> <p>When the unit is in “<i>analysis phase</i>”, the calculated result values are printed.</p>
Reading+Step	Prints Current, max and min readings of all the displayed channels	<p>If in SCAN mode i.e. current display is Gauging Mode result Screen, the display is changed to STATIC mode and the current displayed channel reading is printed. Each PRINT will advance to the next channel and prints the reading. After the last channel selected for scan is printed, the display reverts back to the first channel.</p> <p>If in STATIC, each PRINT will advance to the next channel and prints the reading. After the last channel selected for scan is printed, the display reverts back to the first channel.</p>	No Operation.	No Operation.
All Readings	Prints Current Reading of all the 31 channels	Prints the current reading of all the channels selected for scanning.	Prints the current reading of all the channels selected for scanning.	All the stored readings and calculated result values are printed. This mode works only when unit is in “ <i>analysis phase</i> ”.

8.8.1 PRINT FORMAT

- Current Readings:

In any mode the current readings of the measurement channels are printed in the format below:

Channel Nr (C1 to C31)				Space	Sign	Reading Right aligned with DP set through "Places after DP" setting in "Display Configuration" menu								Space	Units				Space	Limits	Carriage Return	Line Feed
C	x		:		+								x		m	m				>	/r	\n
C	x	x	:		-							x	.	x	i	n	c	h		<		
										x	.	x	x	x	d	e	g			=		
									x	.	x	x	x	x	r	a	d			!		
								x	.	x	x	x	x	x								
													x	x								
												x	x	.	x							
									x	x	.	x	x	x								
								x	x	.	x	x	x	x								
							x	x	.	x	x	x	x	x								
													x	x	x							
												x	x	.	x							
									x	x	x	.	x	x								
							x	x	x	.	x	x	x	x								
						x	x	x	.	x	x	x	x	x								
						x	x	x	.	x	x	x	x	x								

Eg: For channel C1 with reading as +1.34815 with units as inch, within limits

C	1	:	+	1	.	3	4	8	1	5	i	n	c	h	=	\r	\n
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	----	----

Limits	Description
>	Above Upper Limit
<	Below Lower Limit
=	Within limits
!	Probe Error - One of the probe used in the formula is not notified or has under range/over range error

- Current, Max, Min Readings:

In any mode Current, Max, Min readings of the measurement channels are printed in the format below:

[illegible]

- PEAK Mode Print Format:

The readings in the PEAK mode are printed in the below format:

Reading Nr						Space	Sign	PEAK Reading										Carriage return	Line Feed
P	n	t	x		:		+										x	\r	\n
P	n	t	x	x	:		-							x	.	x	x		
												x	.	x	x	x			
											x	.	x	x	x	x			
										x	.	x	x	x	x	x			
									x	.	x	x	x	x	x	x			

Eg: PEAK readings values +7.4982, +10.6290 and +9.1863 are displayed as below

P	n	t	1		:		+			7	.	4	9	8	2	\r	\n
P	n	t	2		:		+		1	0	.	6	2	9	0	\r	\n
P	n	t	3		:		+			9	.	1	8	6	3	\r	\n

The calculated result values are printed in the below format:

Result Type											Space	Sign	Result value													Carriage return	Line Feed
M	a	x	:					:			+													x	\r	\n	
M	i	n	:					:			-													x	.	x	
R	a	n	g	e				:																x	.	x	
A	v	e	r	a	q	e	:																	x	.	x	

Eg: Max=+7.4982, Min=+7.3716, Range=+0.1266 and Average=+7.3915																									
M	a	x	:				:	+					7	.	4	9	8	2	\r	\n					
M	i	n	:				:	+					7	.	3	7	1	6	\r	\n					
R	a	n	g	e			:	+					0	.	1	2	6	6	\r	\n					
A	v	e	r	a	g	e	:	+					7	.	3	9	1	5	\r	\n					


8.9 SERIAL PORT MENU

Serial Port Menu		OPTIONS	
Baud Rate		1200, 2400, 4800, 9600, 19200, 38400, 57600, 115200, 187500	
No of Data Bits		7, 8, 9	
No of Stop Bits		0.5, 1, 1.5, 2	
Parity		Odd, Even, None	
Exit Menu			

Pin diagram of RS232 port:

PIN	Description
1	Not Used
2	RS232 Tx
3	RS232 Rx
4	Not Used
5	RS232 GND
6	Not Used
7	Not Used
8	Not Used
9	Not Used

8.10 ADVANCED MEASUREMENT MODE MENU



To switch OFF the advanced measurement mode and return back to the OPERATE SCREEN mode, select NONE.

8.10.1 PEAK MODE

Advanced Measurement Mode Menu		OPTIONS
Advanced Mode		None, Gauging, Autosense, PEAK mode
Channel Nr		1 to 31
No. of Readings		2 to 99
Exit Menu		

PEAK mode is designed to take up to 99 numbers of PEAK readings as input, analyze the same and display the calculated result values. When PEAK mode is selected, the unit enters into “*acquisition phase*” and the selected channel reading is displayed in single channel mode. User can set the current displayed reading as a PEAK reading through “ENTER” key press. The storage counter displayed on the screen gets incremented after a successful store of the PEAK reading. If an input reading has to be erased, the same can be done by PEAK/TRACK key press. When all the configured number of PEAK readings is input, the unit enters into “*analysis phase*” and the readings are analyzed and below mentioned calculated result values are displayed through a result message pop-up window:

Max: Maximum PEAK reading in all the PEAK readings input

Min: Minimum PEAK reading in all the PEAK readings input


Range: (Max – Min)

Avg: Sum of all readings/Number of readings input

When the result message pop-up window is exit, all the current readings are erased and the unit is ready to take next set of input readings.

User can print the stored PEAK readings and the calculated result values according to the PRINT mode settings configured. Refer to [PRINT Options](#) section for further details.

8.11 UTILITIES MENU




Lock Menu – Will lock the MENU key. A valid password has to be entered whenever MENU screens has to be opened. No password is required for other key press functionalities.

Lock All – A valid password has to be entered for MENU key press. All the other keys will be disabled and does not function.

Button Lock – Will lock all the keys. A valid password authentication is required for any key press.

8.11.1 LOGGING SETTINGS



This menu screen allows user to configure the required logging settings. The required number of channels for logging can be selected through “Channel Count” option. NOTE THAT the “Duration” and “Interval” time values have to be multiple of 20ms. User can log up to 8 sets of data onto

FLASH through selecting one of Page1 to Page8. Each “Page” is of 512KB in size and can hold up to 4K readings from each measurement channel when all the 31 channels are selected for logging. The number of readings can increase if less than 31 channels are selected for logging. The “Start Logging” option will start logging the data onto RAM and not onto FLASH. User has to save the data onto FLASH through “Save Log” option. “Print Log” and “Print Summary” options send the data through RS232 port.

Log Mode Options:

Standard – This mode is time triggered logging mode. In this mode the logging can be started/stopped through Start Logging/Stop Logging menu options. The logging is automatically switched OFF after the configured duration time is elapsed.

Start on I/P – This mode is similar to “Standard” mode except that the logging can be started through LOG digital input only. Logging cannot be started through “Start Logging” menu option in this mode. Logging can be stopped through “Stop Logging” menu option or it is switched OFF after the configured duration time is elapsed in this mode. Refer to [Pin Details of Discrete Inputs](#) section for digital inputs pin diagram.

Trig. on I/P – In this mode a snapshot of the current readings are logged whenever there is an active input on LOG digital input pin. User has to start logging through “Start Logging” menu option before logging of current readings can happen. Logging can be stopped through “Stop Logging” menu option only and automatic logging switch-OFF is not present in this mode. Refer to [Pin Details of Discrete Inputs](#) section for digital inputs pin diagram.

Log Page Select Options:

Current – Selects the log data stored in RAM. This option is not available in “Save Log” option.

Page1 to Page8 – Selects the log data set stored in the selected FLASH page.

Log Summary printed will contain the below information per channel:

Number of Readings: Number of readings logged per channel

Max Reading of Ch: Maximum reading

Min Reading of Ch: Minimum reading


Limit> Ch: Number of readings above the upper limit

Limit< Ch: Number of readings below the lower limit

Mean Ch: Mean of the readings


StdDev Ch: Standard Deviation of the readings

8.11.2 SCREEN SETTINGS



LCD screen contrast setting can be adjusted with the provided contrast levels options.


8.11.3 ABOUT



About Menu screen display firmware version of both MICRO1 and MICRO2. It is displayed in the format <MICRO1 Ver><MICRO2 Ver>.

9 SETTING UP PROBES

- After making the connections as explained in [ELECTRICAL INSTALLATION](#) section, go to SetUp Menu Page-1 through MENU Key and then select “Probes” option to enter the Probes Menu.
- In “Probes” menu, select the direction as Retract+ for Spring-Push type probe and as Extend- for Pneumatic type probe and select NOTIFY. The NOTIFY screen will be displayed with an on-screen tip.
- In the NOTIFY screen, NOTIFY option will no longer be available instead Cancel option will be available. The probe tip should be moved in such a way that the readings change by more than 1%.
- After the NOTIFY procedure is completed, all the parameters are populated according to the probe type. Move to the next probe through “Next Menu”.
- Follow the same procedure to NOTIFY all the connected probes. This completes the probes setting-up procedure. The formula for individual measurement channel can be configured through [computed measurement](#) section.



9.1 SETUP STEPS BEFORE STARTING MEASUREMENT

After setting up the probes as described in [Setting up probes](#) section, the probe readings has to be reset to a known initial value before starting the measurement. Below procedure has to be followed **in the same order as mentioned** before starting the measurement:

- Perform a PEAK reset on all the probes - Exit from menu screen and set the display in OPERATE screen mode to display the current readings. Hold DOWN key for 1sec to perform the PEAK reset on all the probes. Alternatively, the operation can also be performed through a discrete input. Refer to [Input/Output Menu](#) section for configuration and pin details of discrete inputs. This step will clear all the previously tracked PEAK+ or PEAK- or run-out values.

NOTE: It takes 0.5sec to perform a PEAK reset on the probe if it is configured in "Difference mode" for tracking MAX/MIN/finding run-out. Wait for the required time according to the number of sensors configured in "Difference mode".

- Perform a ZERO operation - This operation will set the current reading of all the channels to Zero. Press ZERO key to perform this operation. Alternatively, the operation can also be performed through a discrete input. Refer to [Input/Output Menu](#) section for configuration and pin details of discrete inputs. Enable ZERO/Preset all setting through [Display Configuration Menu](#) to perform ZERO operation on all the channels at once.
- Instead of ZERO operation, PRESET operation can be performed according to the user requirements. Press UP arrow key to add pre-defined PRESET values. Alternatively, the operation can also be performed through a discrete input. Refer to [Input/Output Menu](#) section for configuration and pin details of discrete inputs. Enable ZERO/Preset all setting through [Display Configuration Menu](#) to perform PRESET operation on all the channels at once.
- User can start taking the measurements now.

10 SERIAL COMMANDS

SI5500 supports two serial PRINT commands named below:

- SI5500 PRINT Command:

This command is used to get the details of a single measurement channel or for all the measurement channels in complete format.

Command bytes – ‘^’ ‘P’ ‘S’ <channel number>. Channel number varies from 0 to 30. If set to 0xFF, details of all the channels are printed.

Print Data Format –

Channel Nr (C1 to C31)				Space	Sign	Reading Right aligned with DP set through "Places after DP" setting in "Display Configuration" menu										Space	Units				Space	Carriage Return	Line Feed
C	x		:		+										x		m	m				\r	\n
C	x	x	:		-								x	.	x		i	n	c	h			
												x	.	x	x		d	e	g				
												x	.	x	x	x		r	a	d			
												x	.	x	x	x							
												x	.	x	x	x							
																x	x						
																x	x	.	x				
																x	x	.	x	x			
																x	x	.	x	x	x		
																x	x	.	x	x	x		
																x	x	.	x	x	x		
																x	x	x					
																x	x	x	.	x			
																x	x	x	.	x	x		
																x	x	x	.	x	x	x	
																x	x	x	.	x	x	x	
																x	x	x	.	x	x	x	
																x	x	x	.	x	x	x	

Eg: For channel C1 with reading as +1.34815 with units as inch, within limits

C	1		:		+				1	.	3	4	8	1	5		i	n	c	h		\r	\n
---	---	--	---	--	---	--	--	--	---	---	---	---	---	---	---	--	---	---	---	---	--	----	----

11 MEASUREMENT AND TIMING INFORMATION

Parameter	Update Rate/Value	Remarks
Data Reading rate from the Orbit Sensors	Every 20ms	This also depends on how many channels use MAX or MIN or DIFF operators in their formula. If we have more channels using these operators, then the data read rate can become slower (can become greater than 20ms).
Data Refresh on the LCD display	30ms after reading the data from the Orbit Sensors	This depends on the complexity of the formula used for the measurement channels. If the complexity is less (less measurement channels are used or less trigonometric functions are used), then the update rate can be faster (can become less than 30ms).
Response to digital input	Within 100ms from the time of setting the input	
Digital Output Update	Within 10ms from the time of reading the data from the Orbit Sensors	
Resolution	<p>18-bit when not in Difference mode</p> <p>14-bit when in Difference mode</p> <p>User can change resolution through Probes Menu.</p>	<p>If MAX or MIN or DIFF operations have to be performed on an Orbit Digital Sensor then it is operated in Difference mode. This is applicable only if the operations are performed on a single sensor and not on a sub-expression involving multiple sensors.</p> <p>For e.g. The resolution is lowered to 14-bit if the formula contains MAX(A) and is not applicable if it contains MAX(A+B).</p>

12 RETURN OF GOODS

Devices returned for service/repair/calibration should be shipped prepaid to your distributor or, if purchased directly from Solartron Metrology, to the relevant Sales Office.

The shipping container should be marked:
'For the Attention of the Customer Services Department'

The following information should accompany the device(s):

1. Contact details of company/person returning device, including return shipping instructions.
2. A statement of service required.
3. Description of the device fault and the circumstances of the failure, including application environment and length of time in service.

Alternatively there is a returns form available on our web site, follow the link to "Service Repair and Recalibration".

Please note:

A standard assessment charge is applicable on all non-warranty devices returned for repair.

Customer damage and any device found, upon inspection, to have no fault will be considered non-warranty.

Please contact the Sales Office or Distributor for warranty terms, service options and standard charges.

Adherence to these procedures will expedite handling of the returned device and will prevent unnecessary additional charges for inspection and testing to determine the condition.

Solartron Metrology reserves the right to repair or replace goods returned under warranty.

All repairs are guaranteed for 3 months (unless other-wise stated).

Solartron Metrology reserves the right to make changes without further notice to any products herein to improve reliability, function or design.

Solartron Metrology does not assume any liability arising out of the application or use of any product or circuit described herein, neither does it convey any licence under patent rights nor the rights of others.